



For welding. Without locking ring. Without gasket.

A souder. Sans verrou. Sans joint.

Para soldar. Sin cierre. Sin junta.

SS 316

20	26,9	510 12 50
25	33,7	510 12 51
32	42,2	510 12 52
40	48,3	510 12 53
50	60,3	510 12 54
65	76,1	510 12 55
80	88,9	510 12 56
100	114,3	510 12 57