



For welding BW.

A souder BW.

Para soldar BW.

ST

1"	33,7	510 51 04
1"1/4	42,2	510 51 05
1"1/2	48,3	510 51 06
2"	60,3	510 51 07
2"1/2	76,1	510 51 08
3"	88,9	510 51 09
4"	114,3	510 51 10
5"	139,7	510 51 11
6"	168,3	510 51 12